

Republic of the Philippines OFFICE OF THE PRESIDENT NATIONAL COMMISSION ON MUSLIM FILIPINOS

BIDS AND AWARD COMMITTE REQUEST FOR QUOTATION – 2024-035

Mode of Procurement: Small Value Procurement

Purpose: Preventive Maintenance Service (PMS)

End-user – ADMIN-GSD Code (PAP):

PR No. 2024 – 05 - 0154 Date: 29 May 2024

Please quote your lowest price for the items/s listed below not later than 3 <u>June 2024</u> subject to the following terms and conditions, and submit your quotation duly signed by your representative by email: or personal delivery at NCMF Central Office (Mondays-Fridays, 8:00 AM - 5:00 PM).

TERMS AND CONDITIONS:

- In order to be eligible for this procurement, suppliers'/service providers are required to accomplish this RFQ and submit on or before the deadline together with the following;
 - a. Valid PhilGEPS Registration Certificate/Number;
 - b. Valid Mayor's/ Business Permit;
 - c. Income/Business Tax Return: (for ABC's above \$700,000.00) w
 - d. Notarized Omnibus Sworn Statement
- 2. Late submission of quotation shall not be accepted.
- 3. Price validity shall be for a period of sixty (60) calendar days.
- Award of contract shall be made to lowest quotation with complete requirements and complies with the specifications and other terms and conditions stated in the RFQ
- Any interlineations, erasures, or overwriting shall be valid only if they are signed or initialed by the supplier or its authorized representative(s).
- The NCMF reserves the right to reject any or all quotations/bid proposals or declares the bidding a failure or not to award the contract, and makes no assurance that a contract shall be entered into as a result of this invitation.
- Liquidated damages equivalent to one-tenth of one percent (0.1%) of the value of the goods not delivered within the prescribed delivery period shall be imposed per day of delay.
- The terms of payment shall be made through check payable to the supplier. All quotations shall be <u>INCLUSIVE OF VAT.</u>

| tem Description | ABC | Comply/Not Comply | QUOTATION |
|--|-----|----------------------|-----------|
| Preventive Maintenance Service (PMS Cleaning of Air Conditioning Units |) | | |



EMAIL: ncmf.osec@gmail.com Website: www.ncmf.gov.ph



| Office | Type of Aircon | Qu ant ity | Remark s |
|--------------|--|------------------|------------------|
| GSD | Hyundai Split Type | 2 | 2.5 HP |
| BLA | Tusot Split Type | 1 | 2.5 HP |
| BMS | Hyundai Split Type | 1 | 2.5 HP |
| BPCR | Hyundai Split Type | 1 | 2.5 HP |
| BMS | Hyundai Split Type | 1 | 2.5 HP |
| BPE | Carrier Spilt Type | 1 | 2.5 HP |
| BMEA | Hyundai Split Type Carrier Split Type | 1 1 | 2.5 HP 2.5 HP |
| Dir. BMEA | Matrix Split Type | 1 | 1.5 HP |
| DED | Ox Split Type | 1 | 2.0 HP |
| OED | Carrier Split Type Ox Split Type | 1 1 | 2.5 HP 2.0 HP |
| MISD | Hitachi Split Type | 2 | 2.5 HP |
| BER | Hyundai Split Type Carrier Floor Type | 2 3 | 2.5 HP 3TR |
| COS | Hyundai Spilt Type | 1 | 2.5 HP |
| BAC | Carrier Split Type | 1 | 2.5 HP |
| PMO | Mobe Split Type | 1 | 2 HP |
| OSEC | Hyundai Split Type LG Window Type | 1 4 | 2.5 HP 2 HP |

| Comm. Mindala no | Hyundai Split Type | 1 | 2.5 HP | |
|---------------------------|--|---|--------------|--|
| Comm. Mindala no | Condura Split Type | 1 | 2.0 HP | |
| Comm. Along | Tusot Split Type | 2 | 2.5HP | |
| NCMFE A | National Split Type | 1 | 1.5 HP | |
| Prayer Room | Ox Split Type | 1 | 2.0 HP | |
| Comm. Macada wan | Ox Split Type | 1 | 2.0 HP | |
| Planning | LG Window Type | 3 | 2 HP | |
| BPE | LG Window Type | 3 | 2 HP | |
| BMS | LG Window Type | 3 | 2 HP | |
| FMS | LG Window Type | 3 | 2 HP | |
| Cashier | LG Window Type | 1 | 2 HP | |
| Admin | LG Window Type | 2 | 2 HP | |
| HR | LG Window Type | 2 | 2 HP | |
| Comm. Mando | Carrier Window Type | 1 | 2 HP | |
| Dir. Cosaine (BPCR) | Kollin Window Type Panasonic Window Type | 1 | 2 HP 1 HP | |
| CRS | Panasonic Window Type Carrier Window Type | 1 | 1 HP 2 HP | |

| COA | Carrier Window Type Carrier Window Type National Window Type | 1 1 1 | 2 HP 1.5 HP 1.0 HP | | |
|------------------------------------|--|-------------|--------------------------|--|--|
| Comm. Mastura | Tusot Window Type Carrier Window Type | 1 1 | 2 HP 2 HP | | |
| Comm. Munib | Tusot Window Type | 1 | 2 HP | | |
| Comm. Lidasan | Tusot Window Type | 1 | 2 HP | | |
| Prayer Room | Carrier Window Type Carrier Window Type | 1 | 2 HP 1.5 HP | | |
| Comm. Mamoki d | Condura Window Type | 1 | 2 HP | | |
| BPE | Carrier Window Type Condura Window Type | 1 1 1 | 1.5 HP 1.0 HP | | |
| BMCA | Hyundai Floor Type | 1 1 | 3TR | | |
| Social Hall | Carrier Floor Ty | 1 | 3TR | | |
| lode of Pa Send bill a LDDAP | yment: irrangement pay | /mer | nt thru | | |

TAHIR S. LIDASAN JR., CESO II Chairman, BAC

| Sig | nature over Printed Name of Representative/ Company |
|-----|---|
| | Address |
| | PHILGEPS: Registration Number (Platinum/Red) |
| | Tel.No.: /Cellphone/Email Address |

RFQ No 2024-035 Small Value Procurement - Preventive Maintenance Service (PMS)